

Mounting and position of the motors

Foot mounted

- B3 Foot mounted (horizontal)
Pattes (à l'horizontale)

Flange Mounted

- B5 Plain holes flange
Bride à trous lisses
- B14 Threaded hole flange mounted
Bride à trous taraudés

Foot + Flange mounted

- B35 Foot + Plain holes flange mounted
Pattes + Bride à trous lisses
- B34 Foot + Threaded hole flange mounted
Pattes + Bride à trous taraudés

