


Plain Clamps

DIN 6314



10000



Material


Heat-treated steel, enamelled.


Technical Notes

() = Not to DIN standard.

For T-bolts, washers and nuts see part 21000 to 24300.

Order No.	b ₁	l	For metric thread	For imperial thread	a	b ₂	b ₃	e ₁	e ₂	 g
10000.W0007	6,6	50	M 6	1/4	10	20	8	10	20	63
10000.W0009	9,0	60	M 8	5/16	12	25	10	13	22	113
10000.W0011	11,0	80	M10	3/8	15	30	12	15	30	226
10000.W0014	14,0	100	M12, M14	1/2	20	40	14	21	40	490
10000.W0015	14,0	125	M12, M14	1/2	20	40	14	21	50	621
10000.W0018	18,0	125	M16, M18	5/8	25	50	18	26	45	960
10000.W0019	18,0	160	M16, M18	5/8	25	50	18	26	65	1240
10000.W0022	22,0	160	M20, M22	3/4	30	60	22	30	60	1787
10000.W0023	22,0	200	M20, M22	3/4	30	60	22	30	80	2237
10000.W0026	26,0	200	M24	1	30	70	26	35	80	2580
10000.W0027	26,0	250	M24	1	(35)	70	26	35	105	3800
10000.W0034	33,0	250	M30	1-1/4	40	80	34	45	100	4934
10000.W0035	33,0	315	M30	1-1/4	50	80	34	45	130	7880
10000.W0043	(43,0)	400	M36, M42	1-1/2	60	100	43	100	150	15000





Material

Heat-treated steel, enamelled.

Technical Notes

() = Not to DIN standard.
For T-bolts, washers and nuts see
part 21000 to 24300.