

# Preventative Maintenance

## Recommended Service A - Recommended every Year



Description	DM012 - DM040	DM050 - DM080	Contents
Kit: Exhaust Silencer	608233670	608330001	1/2" Silencer

Note: One kit is recommended for each dryer.


## Recommended Service B - Recommended every Year



Current Parker domnick hunter Filter Service Kits to be supplied as standard. Please check the filter housing model numbers for correct element suitability.

## Recommended Service C - Recommended every 2 Years

Description	DM012 - DM025	DM030 - DM040	DM050 - DME080	Contents
Kit: Valve Overhaul	60-823-3690	60-823-3691	60-823-3692	Inlet Valve Kit, Outlet Valve Kit, Exhaust Valve Kit, Control Valve Kit



Description	DM012 - DM025	Contents
Kit: Inlet Valve	608233671	ISO 2 Control Valve, Fixing screws



Description	DM030 - DM040	Contents
Kit: Inlet Valve	608233672	5 Port spool valve, Gasket, Fixing screws