



TYPE

Connection between machine spindle and chucking tool head (e.g. drill chuck)
Jacobs drill chuck taper DIN 238

A04 Taper shank arbors with Jacobs drill chuck taper

Item no.	Morse taper DIN 228 B	Hole for alignment pin	L mm	A mm	C mm	E mm	G mm	H mm	Weight
014970	1	J1	86,5	62	12.065	16.7	9.754	8.5	50
014971	1	J2	92	62	12.065	22.2	14.199	12.4	70
014972	1	J3	101	62	12.065	31	20.599	19	50
014974	1	J6	95	62	12.065	25.4	17.17	15.9	50
014976	2	J1	101	75	17.78	16.7	9.754	8.5	130
014977	2	J2	106,5	75	17.78	22.2	14.199	12.4	160
014978	2	J3	115,5	75	17.78	31	20.599	19	200
014981	2	J6	109,5	75	17.78	25.4	17.17	15.9	165
014980	2	J33	109,5	75	17.78	25.4	15.85	14.2	160
014983	3	J2	126	94	23.825	22.2	14.199	12.4	310
014984	3	J3	135	94	23.825	31	20.599	19	350
014988	3	J6	129	94	23.825	25.4	17.17	15.9	310
014987	3	J33	129	94	23.825	25.4	15.85	14.2	310
014991	4	J3	161	117.5	31.267	31	20.599	19	475
014995	4	J6	155	117.5	31.267	25.4	17.17	15.9	620

