

Quick-clamping Nut SDS-*clic*

- **Observe the safety warnings for the power tool you are using.**
- **Use the quick-clamping nut 1 603 340 031 only for bonded grinding and cutting discs and for diamond cutting discs on an angle grinder with M14 grinder spindle thread – see figure A2.**
- **Use the quick-clamping nut 2 608 000 638 for bonded grinding and cutting discs, for diamond cutting discs and also for carbide cup wheels only on a Bosch angle grinder with magnetic brake function with M14x1.5 grinder spindle thread – see figure A2.**
- **Use only a flawless, undamaged quick-clamping nut 3.**

Clean the grinder spindle **5**, the mounting flange **4** and the quick-clamping nut **3**.

When screwing on, pay attention that the labelled side of the quick-clamping nut **3** does not face toward the grinding disc; the arrow must point toward the index mark **2** – see figure A1.